


---

## GENERAL INFORMATION

Roof Name	Roof 01.1 (L2)
Service Activity Type	No
Service Activity Date	
Year of Installation	
Installing Contractor	
Roof Leaks	
Roof Size	5,130 sq. ft. 476.77 sq. meters
Roof Type	PVC
Roof Rating	Fair



## ROOF COMPOSITION

Single Ply PVC

## OVERALL CONDITION

This roof appears to be in fair condition.

## RECOMMENDATIONS

To maintain the current assets of the system, this roof should be budgeted for a restoration prior to it surpassing its serviceable life.

---

**Service Activity Photos**

---



View of Roof 1.1 prior to being cleaned.



Overview of the roof in the process of being cleaned.



Another view of the roof being cleaned,



Overview of Roof 1.1 with the roof cleaning complete.

---